

Fujitsu Image Scanners

Options, Consumables and Spare Parts

“... a collection of useful part numbers”

Revision History

Revision	Page numbers	Description
001	1,3,5	ScanPartner 600C added. Various additions and corrections.
002	1	ScanPartner 600C revised.
003	1	ScanPartner 10C & ScanPartner 600C revised.

Table Of Contents

SCANPARTNER SERIES	1
SCANPARTNER JUNIOR (SCSI)	1
SCANPARTNER 10C	1
SCANPARTNER 600C	1
SCANPARTNER EO (M3192B)	1
M309X SERIES CURRENT PRODUCT	2
M3093EX/GX	2
M3093DE/DG	2
M3096EX/GX	2
M3097E/G & M3097E+/G+	3
M3099EX/GX/EH/GH	3
M309X SERIES OLD PRODUCT.....	4
M3093E	4
M3094E/95E	4
M3096E+/G	4
M3099A/G	5
MISCELLAENEOUS	6

ScanPartner Series

ScanPartner Junior (SCSI)

Description	Part no.	Comments
Led array assembly	003-5012-0	
Pad unit	003-5002-Z	
Separating roller assembly	003-5003-0	

ScanPartner 10C

Description	Part no.	Comments
White lamp	060-0029-0	2,000 hours
Red lamp	060-0031-0	
Pad and touch spring unit	003-0006-0	50,000 sheets or 1 yr.
Scrub roller (pick roller)	008-0001-0	
Feed Roller	008-0002-0	2 for each ADF

ScanPartner 600C

Description	Part no.	Comments
CCFL assembly (lamp)	003-5076-0	15,000 hours
Pad and touch spring unit	003-0006-0	50,000 sheets or 1 yr.
Scrub roller (pick roller)	008-0001-0	
Feed Roller	008-0002-0	2 for each ADF

ScanPartner EO (M3192B)

Description	Part no.	Comments
Image sensor unit (front side)	CA02580-E455	
Image sensor unit (back side)	CA02580-E535	For revision B2 and lower only
Image sensor unit (back side)	CA02580-E537	For revision B3 and higher only
Business card holder	CA02580-E255	
Pad assembly	CA02580-F326	20,000 sheets or 1 yr.

M309x Series current product

M3093EX/GX

Description	Part no.	Comments
Green lamp	PA02212-F030	2,500 hrs.
Red lamp R61	PA54001-0011	2,500 hrs.
Image processing circuit (IPC-2)	CA01952-0191	
Memory compression unit (CMP-2)	CA01952-0196	M3093GX
Pad assembly	PA02201-0020	100,000 sheets or 1 yr.
Pick roller	PA02212-Y080	200,000 sheets or 1 yr.

M3093DE/DG

Description	Part no.	Comments
Green lamp (front side)	PA02212-F030	2,500 hrs.
Green lamp (back side)	PA54001-0017	2,500 hrs.
Red lamp R61 (front side)	PA54001-0011	2,500 hrs.
Red lamp R61 (back side)	PA54001-0018	2,500 hrs.
Image processing circuit (IPC-2D)	CA01952-0192	
SIMM memory 8MB	CA02939-B182	
Pad assembly	PA02201-0020	100,000 sheets or 1 yr.
Pick roller	PA02212-Y080	200,000 sheets or 1 yr.

M3096EX/GX

Description	Part no.	Comments
Green lamp	PA02201-F102	2,500 hrs.
Red lamp R66	PA54001-0010	2,500 hrs.
Image processing circuit (IPC-2)	CA01952-0191	
Memory compression unit (CMP-2)	CA01952-0196	M3096GX
Pad assembly	PA02201-0020	100,000 sheets or 1 yr.
Pick roller	PA02201-Y978	200,000 sheets or 1 yr.

M3097E/G & M3097E+/G+

Description	Part no.	Comments
Green lamp	U49L-0050-0017	500 hrs. or 30,000 on/off cycles
Red lamp R66	PA54001-0004	500 hrs. or 30,000 on/off cycles
Image processing circuit (IPC-2)	CA01952-0191	
Memory compression unit (CMP-2)	CA01952-0196	M3097G/M3097G+
Pad	PA02201-E090	100,000 sheets or 1 yr.
Pick roller	PA02201-Y960	200,000 sheets or 1 yr.

M3099EX/GX/EH/GH

Description	Part no.	Comments
Green lamp	CA02950-0548	500 hrs. or more (2 lamps per scanner required)
Red lamp R66	CA02950-0866	500 hrs. or more (2 lamps per scanner required)
Endorser	CA01023-D004	
Print head (for endorser)	CA01023-0701	20,000 sheets (at 10 chars. per sheet)
Pad	CA01023-G290	300,000 sheets or 1 yr.
Pick roller (grey)	CA01023-F242	300,000 sheets or 1 yr.
Pick roller (black)	CA01023-F244	300,000 sheets or 1 yr.
Separation belt	CA02869-Y223	300,000 sheets or 1 yr.
Roller assembly	CA02869-F230	600,000 sheets or 1 yr.
Belt assembly	CA02869-F220	600,000 sheets or 1 yr.

M309x Series old product

M3093E

Description	Part no.	Comments
Green lamp	B49L-0410-0001A	500 hrs.
Red lamp R61	U11B-8032-E022	500 hrs.
Pad assembly	U110-8032-V100	100,000 sheets
Image processing circuit (IPC)	B01L-4440-0101A	MAS4-OP (U16B-0429-0500)

M3094E/95E

Description	Part no.	Comments
Green lamp	U49L-0050-0006	M3094E
Green lamp	U49L-0050-0007	M3095E
Red lamp 61	U49L-0050-0018	M3095E
Red lamp 66	PA54001-0003	M3095E
Pad assembly	U110-8035-V760	100,000 sheets or 1 yr.
Dynamic threshold circuit	B01L-4450-0501A	MAS-OP

M3096E+/G

Description	Part no.	Comments
Green lamp	U49L-0050-0007	
Red lamp R66	PA54001-0003	
Pad assembly	U110-8035-V760	100,000 sheets or 1 yr.
Memory compression unit (CMP)	B01L-4560-0201A	M3096G
Image processing circuit (IPC)* ¹	B01L-4560-0101A	
Dynamic threshold circuit (DTC)* ¹	B01L-4450-0501A	M3096E+ only

*¹ In M3096E+ DTC and IPC cannot be installed together

M3099A/G

Description	Part no.	Comments
Green lamp	CA02950-0548	500 hrs. or more (2 lamps per scanner required)
Red lamp R66	CA02950-0866	500 hrs. or more (2 lamps per scanner required)
Image processing circuit (IPC-2)	CA01952-0191	(2 boards per scanner)
Endorsement unit	CA01023-D004	
Print head	CA01023-0701	20,000 sheets (at 10 char. per sheet)
Pad	CA01023-G290	300,000 sheets or 1 yr.
Pick roller (grey)	CA01023-F242	300,000 sheets or 1 yr.
Pick roller (black)	CA01023-F244	300,000 sheets or 1 yr.
Separation belt	CA01023-Y223	300,000 sheets or 1 yr.
Roller assembly	CA02869-F230	600,000 sheets or 1 yr. (remove shims from green ADF levers when using this part)
Belt assembly	CA01023-F223	600,000 sheets or 1 yr.
<i>or the following parts (old style)</i>		
Separation belt	CA01023-W224	300,000 sheets or 1 yr.
Roller assembly	CA01023-F232	600, 000 sheets or 1 yr.
Belt assembly	CA01023-F222	600, 000 sheets or 1 yr.

Note: Roller assembly CA01023-F232 and separation belt CAO1023-W224 (or belt assembly CAO1023-F222) must be used together .

Miscellaeneous

Description	Part no.	Comments
Grease for lubrication	B98L-0020-0012A	50g
Oil for lubrication	D98L-1020-0638	50ml
Silicon-Oil		